

E_n	F_s	$\frac{E_n}{F_s}$	W_0
34	45	0.76	21
35	57	0.61	8

(Sheet B)

42	56	0.75	2
35	62	0.56	3
36	62	0.58	2
37	61	0.61	2
37	60	0.62	3
36	61	0.59	3
38	60	0.63	2
36	63	0.57	2
37	59	0.63	5
36	58	0.62	6
36	58	0.62	6
32	64	0.50	4
37	61	0.61	2
36	61	0.59	3
36	61	0.59	3
38	61	0.62	2
37	62	0.60	2
34	46	0.74	21
36	62	0.58	2
38	60	0.63	2
38	56	0.68	6
35	58	0.66	4
38	60	0.63	2
38	60	0.63	2
37	62	0.60	2
38	60	0.63	2
36	56	0.64	8
34	62	0.58	3
38	61	0.62	2

E_n	F_s	$\frac{E_n}{F_s}$	W_0
35	61	0.57	4
34	54	0.63	12
36	63	0.57	2
35	51	0.69	14

36	62	0.58	2
36	57	0.63	6
36	61	0.59	3
36	61	0.59	3
38	60	0.63	2
37	61	0.61	3
37	61	0.61	2
35	54	0.65	11
29	31	0.93	40
38	60	0.63	2
29	29	1.00	41
37	61	0.61	2
36	61	0.59	3
36	59	0.61	4
33	59	0.56	8
34	52	0.65	14
38	61	0.62	2
38	60	0.63	2
38	57	0.67	5
37	61	0.61	2
38	61	0.62	2
35	62	0.56	4
37	57	0.65	6
38	60	0.63	3
35	58	0.60	7

Sheet D

35	58	0.60	8
37	60	0.62	3

	$E_n : F_s$	$\frac{E_n}{F_s}$	W_0	$E_n : F_s$	$\frac{E_n}{F_s}$	W_0
Z-1	37 : 61	0.61	2	36 : 60	0.60	4
	34 : 51	0.67	15	36 : 60	0.60	4
	37 : 61	0.61	2	36 : 60	0.60	4
	35 : 57	0.61	8	35 : 53	0.66	12
	33 : 49	0.67	18	35 : 56	0.63	8
	38 : 60	0.63	2	37 : 60	0.62	3
	37 : 56	0.66	8	37 : 61	0.61	2
	36 : 54	0.67	10	36 : 60	0.60	5
	37 : 61	0.61	2	37 : 61	0.61	2
	38 : 60	0.63	2	37 : 61	0.61	2
	38 : 61	0.62	2	39 : 60	0.65	2
	38 : 61	0.62	2	37 : 62	0.60	2
	37 : 61	0.61	2	34 : 64	0.53	2
	37 : 61	0.61	2	35 : 59	0.59	6
	38 : 61	0.62	2	33 : 55	0.60	12
	38 : 60	0.63	2	31 : 27	1.15	42
	38 : 60	0.63	2	34 : 55	0.62	11
	37 : 61	0.61	2	34 : 55	0.62	11
	33 : 49	0.67	19	33 : 51	0.65	16
	33 : 50	0.66	17	34 : 46	0.74	21
	38 : 61	0.62	2	35 : 59	0.59	6
	39 : 59	0.66	2	35 : 60	0.58	4
	36 : 62	0.58	2	33 : 48	0.69	19
	37 : 61	0.61	2	33 : 50	0.66	17
	35 : 53	0.66	12	33 : 52	0.63	15
	36 : 62	0.58	2	35 : 51	0.57	14
	35 : 62	0.56	3	35 : 58	0.60	7
	37 : 60	0.62	3	34 : 49	0.69	17
	35 : 56	0.63	7	34 : 51	0.67	16
	36 : 53	0.70	11	34 : 49	0.69	17
	35 : 59	0.59	6	35 : 55	0.64	10
	35 : 57	0.61	8	33 : 47	0.70	20
	35 : 61	0.57	4	35 : 61	0.57	4

5th page

E_n	F_s	$\frac{E_n}{F_s}$	W_0
38	60	0.63	2
36	61	0.59	3
39	60	0.65	2
35	52	0.67	14
32	35	0.91	33
37	61	0.61	2
37	58	0.64	4
38	60	0.63	2