### AGEE SCREEN COMPANY

## AGEE FLY SCREENS



FORT WORTH, TEXAS, February 24, 1941

Mr. Amon G. Carter, Chairman Citizens Bond Issue Campaign Committee 400 West Seventh Fort Worth, Texas

Dear Mr. Carter:


Mr. H. L. Agee was not able to be present at your meeting which was called for 3 o'clock this afternoon in reference to the bond issue to be held on March 4, for the construction of the U.S. Army Bomber Assembly Plant, as he is still in the hospital from the accident he had in the early part of January.

Although, he was not able to be there in person I feel sure that he was with you in spirit, and that he fully approves of the efforts being put forth on this matter.


ery truly yours,

JEH: TFW


#### AGEE FLY SCREENS




No. 7 CP-23 1%" Thick 4" Stiles (3%" net) 12" Bottom (11%" net)




No. 22 CP-28 1%" Thick 4" Stiles (3%" net) 7%" Bottom Rail





No. 5 CP-27 1%" Thick 4" Stiles (3%" net) 7%" Bottom Rail



No. 5 CP-16 1¼" Thick 3" Stiles (2¾" net) 5½" Bottom Rail









NO. LCN OIL CHECK




No. 66 Adjustable Brass Screen Door Grilles



No. 66 **Enlarged Section** Standard Size 1½ Mesh—24" High






14MESH

Galvanized, Pearl, or Bronze Also 18 Mesh and Finer


Baseballs, etc.—a Combination



Screen.

BRASS OR STEEL GUARD RAILS FOR SCREEN DOORS

#### AGEE FLY SCREENS




No. 2 CP-21 11/8" Thick 2¾" Stiles


2%" Center Rails

14" Mullions


51/2" Bottom Rail




No. 0 CP-1 13" Thick 2¾" Stiles 25%" Center Rails Lower Mullion 51/2" Bottom Rail



METAL FRAME SCREENS **FOR** ALL TYPES OF **WINDOWS** 






Agee's Screen Hangers Are the Best to be Had-Nothing Like It

#### I'll Tell You the Reason Why:

- 1. Because the hooks are on the INSIDE.
- They hang to the blind stop and SEVEN-EIGHTHS SCREENS can be hung to ONE AND ONE-EIGHTHS INCH or any other thickness brick mold or casing without ALTERATION.
- 3. They can be ENLARGED or DISENGAGED with very little effort.
- 4. They hold the screen frame tight against blind stop and DO NOT RATTLE.
- 5. Screens WILL NOT COME OFF of hooks in washing windows.
- 6. They hold screen frames CLOSED even if bottom hooks are unfastened.
- They require no SCREWS IN CORNER of screen frames which is the life of your screen.
- 8. Should your screen swell or for any reason need refitting the hangers do not have to be REMOVED.
- 9. They are put on from the INSIDE of your building and screens on a TWENTY-STORY building may be as easily and RAPIDLY installed as on a one or two-story building.

  10. They are CHEAPER than any other hanger when you consider the LITTLE TIME it takes to install them.


11. They are practically INVISIBLE from either outside or inside.




Wire Window Guard in Place Made on Round Iron Frame

# These Attractive BURGLAR GUARDS


Furnish Maximum
Protection



No. 120 Heavy Wire Window Guard with Channel Iron Frame




ENLARGED SECTION OF GUARD SHOWN ABOVE



ORNAMENTAL GUARD
FOR
SCREEN DOORS

These Wrought
Iron Grilles
For Doors and
Windows
are
Both Ornamental
and Serviceable



ORNAMENTAL GUARD FOR WINDOW SCREENS